

Algonquin Rd. at the Union Pacific freight line between Mt Prospect and Wolf

This is a very difficult place for bikes to navigate. The road narrows towards the crossing, and traffic is often pretty heavy. You've got a choice between an uneven, debris-strewn shoulder and riding right on the white painted line, with a hazardous edge of pavement just adjacent (drop of several inches, enough to throw you off balance. All that is needed here is maybe 18" of additional asphalt outside the traffic lane.

